


4600

profile

4600

137 gr/m



bending

radius

R 10 (1012)



R 10 (1015)

R > 80 (1018)

filler position




Mounting ceiling



ceiling mounting with ceiling mounting clamp 2650(incl. washer), with wood screw 261.

ceiling mounting 4600 with ceiling mounting clamp 2650 + washer, before (a) and after (b) fastening the ceiling mounting clamp



when mounting a curved rail, place a ceiling mounting clamp before as well as after the curve

G-Standard

